

Figure 1A





Figure 1B



Coniferous Wood Anatomy

Figure 2


BEST AVAILABLE COPY




Bordered Pit

Figure 3

BEST AVAILABLE COPY



Cross section of
micronized copper
hydroxide treated
wood sprayed with
copper indicator



Cross section of
untreated wood
sprayed with copper
indicator

Figure 4A

BEST AVAILABLE COPY




Figure 4B

BEST AVAILABLE COPY




Figure 5